

DES-6321^{Q&As}

Specialist - Implementation Engineer - VxRail Appliance Exam

Pass EMC DES-6321 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.certbus.com/des-6321.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



QUESTION 1

You are expanding the capacity of a Hybrid VxRail by creating an additional disk group. The new disk group will be composed of five drives on all participating cluster nodes. When you attempt to add the new disks to the vSAN datastore you receive an error message about there being no cache tier available.

What is the likely cause?

- A. vSAN supports disk groups with four drives or fewer
- B. Cluster requires vSAN Advanced or Enterprise license upgrade
- C. You attempted to add the disks to the existing disk group
- D. All the drives are labeled as HDDs

Correct Answer: D

QUESTION 2

In addition to the VxRail YouTube video, links to what resources should the SE send to the customer, according to the VxRail PEQ Engagement Details worksheet?

- A. VxRail vCenter Server Planning Guide VxRail Network Guide
- B. VxRail QuickStart Guide VxRail Network Guide
- C. VxRail vCenter Server Planning Guide Network Validation Tool
- D. VxRail QuickStart Guide Network Validation Tool

Correct Answer: D

QUESTION 3

In a 24 node Stretched Cluster VxRail deployment, what is the acceptable Round Trip Time (RTT) latency between sites?

- A. Primary to witness site RTT latency: 10 ms
Secondary to witness site RTT latency: 10 ms
Primary to secondary site RTT latency: 10 ms
- B. Primary to witness site RTT latency: 50 ms
Secondary to witness site RTT latency: 50 ms
Primary to secondary site RTT latency: 6 ms
- C. Primary to witness site RTT latency: 75 ms
Secondary to witness site RTT latency: 75 ms
Primary to secondary site RTT latency: 1 ms
- D. Primary to witness site RTT latency: 75 ms
Secondary to witness site RTT latency: 150 ms
Primary to secondary site RTT latency: 5 ms

Correct Answer: A

<https://www.emc.com/collateral/white-papers/h15275-vxrail-planning-guide-virtual-san-stretched-cluster.pdf>(page 6)

QUESTION 4

A VxRail Cluster setup with P570F nodes is used for product evaluation purposes at customer sites. Before moving the Cluster to another customer site, it needs to be reset.

Where is the image located to complete this task?

- A. SATADOM
- B. IDSDM
- C. BOSS
- D. MB Server

Correct Answer: B

QUESTION 5


A VxRail Stretched Cluster deployment will have E560F node. The Cluster must allow local protection with both erasure coding options at either site. What is the minimum node configuration?

- A. 3+3 nodes
- B. 4+4 nodes
- C. 6+6 nodes
- D. 8+8 nodes

Correct Answer: B

QUESTION 6

View the Exhibit.



Based on the exhibit, which interfaces should be used to reset the node through the Mobile Build Server?

- A. 1 and 3
- B. 1 and 2
- C. 2 and 3
- D. 1, 2 and 3

Correct Answer: A

QUESTION 7

What is a requirement for Top-of-Rack (ToR) switches when deploying a VxRail cluster?

- A. Must be manufactured by Dell, Cisco, or Brocade
- B. Must support IPv6 Multicast
- C. Must have two switches in the cluster
- D. Must support 25GbE connectivity

Correct Answer: B

QUESTION 8

When validating the VxRail health just after the VxRail initial configuration, there is a red exclamation mark on the MARVIN-Virtual-SAN-Cluster and the reported health alarm is `Component metadata health\`. A "Retest" action in the health service panel is performed and all the nodes in the cluster show health status as failed with the invalid state. Investigation does not reveal any hardware issues with the disks in use by vSAN. What action should be taken next?

- A. Wait 24 hours, then click the "Retest" button again
- B. Apply the vSphere ESXi600-201611001 patch, then click the "Retest" button again
- C. Evacuate and destroy the disk/disk group that contains the component(s) reporting errors and clear the alarm
- D. Reapply the MARVIN storage policy to the VxRail internal virtual machines

Correct Answer: D

QUESTION 9

You have been asked to install a 7 node VxRail single socket 1 GbE G Series cluster. The company has requested remote KVM support. How many RJ45 cables will be required?

- A. 14
- B. 21
- C. 28
- D. 35

Correct Answer: A

<https://www.emc.com/collateral/technical-documentation/h15104-vxrail-appliance-techbook.pdf>

QUESTION 10

The vSAN health check is reporting errors about the stats.db object. What could be a possible cause of this problem?

- A. vSAN performance service is not enabled on one of the ESX nodes
- B. vSAN health service is disabled
- C. There are inaccessible/unhealthy vSAN objects
- D. vSAN performance service is not enabled

Correct Answer: D

QUESTION 11

A company has chosen to deploy an external vCenter/PSC. They would like to use the bundled vCenter license that comes with VxRail.

What is the correct procedure to do this?

- A. Contact EMC Licensing to have a replacement vCenter license generated. Next, license the newly created vCenter. Last, deploy VxRail with external vCenter.
- B. Contact VMware Licensing to have a replacement vCenter license generated. Next, license the newly created vCenter. Last, deploy VxRail with external vCenter.
- C. Log into VxRail Manager through SSH and extract the vCenter license key from the application properties file. Next, license the newly created vCenter. Last, deploy VxRail with external vCenter.
- D. Bundled vCenter license is only valid when vCenter is internally deployed. The company must provide their own vCenter license.

Correct Answer: D

QUESTION 12

A workstation is being configured on the management VLAN (10.150.140.0/24) to connect to VxRail Manager for first time deployment.

Configuring which IP addresses on the workstation will result in a successful deployment without having to change them during initialization?

- A. 192.168.1.199 and 10.150.140.100
- B. 192.168.1.250 and 10.150.140.255
- C. 192.168.10.199 and 10.150.140.255
- D. 192.168.10.250 and 10.150.140.250

Correct Answer: A

QUESTION 13

Which network traffic types require the specification of a VLAN ID in the VxRail Pre- Installation Site Checklist?

- A. Fault Tolerance, vMotion, vSAN, and user VM Network
- B. Management, vMotion, and vSAN only
- C. Management, vMotion, vSAN, and user VM Network
- D. vMotion, vSAN, and user VM Network only

Correct Answer: B

QUESTION 14

When populating the VxRail First Run Wizard for an External vCenter solution what is the recommended format for hostnames?

- A. vCenter, PSC, and VxRail Manager use host name only
- B. vCenter and PSC use FQDN; VxRail Manager uses host name onl
- C. VxRail Manager and vCenter use FQDN; PSC uses host name only
- D. vCenter, PSC, and VxRail Manager use FQDN

Correct Answer: A

QUESTION 15

A failure occurs during the deployment of a VxRail cluster. You need to look through the marvin.log file to see what could be causing the error. Where is this file located?

- A. var/log/vmware/marvin
- B. var/log/vmware
- C. var/log/vmware/marvin/tomcat/logs
- D. var/log/mystic

Correct Answer: C

Reference: <https://www.javydekoning.com/vxrail-monitoring-managing/>

[Latest DES-6321 Dumps](#)

[DES-6321 VCE Dumps](#)

[DES-6321 Exam Questions](#)