

NS0-593^{Q&As}

NetApp Certified Support Engineer ONTAP Specialist

Pass NetApp NS0-593 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.certbus.com/ns0-593.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by NetApp
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



QUESTION 1

After a motherboard replacement on a NetApp AFF A300 in a SAN environment, the customer states that ports 0e and 0f are unable to connect to the fabric. The ports report "offline".

What would you examine first to troubleshoot the issue?

- A. vserver fcp wwpn-alias show command output
- B. system node hardware unified-connect show command output
- C. storage port show command output
- D. vserver fcp interface show command output

Correct Answer: C

QUESTION 2

You have recently discovered that NetApp ONTAP Cloud Manager is not sending AutoSupport messages to NetApp. In this scenario, what would solve this Issue?

- A. Verify that your AWS credentials are correctly added to Cloud Manager.
- B. Verify that your NetApp Support site credentials are correctly added to Cloud Manager.
- C. Verify that your data LIFs allow traffic to mysupport .netapp.com on port 443.
- D. Verify that the inbound and outbound rules allow AutoSupport on port 80.

Correct Answer: C

QUESTION 3

You recently discovered the error message shown below in your ONTAP logs.

```
[waf1.incons.userdata.vol:error]: WAFL inconsistent: volume my_data_vol
```

What should be your first action to correct this Issue?

- A. Power cycle all the disk storage shelves that contain drives of the aggregate with the my_data_vol volume.
- B. Determine the root cause behind the inconsistency before attempting any recovery procedure.
- C. Use the storage takeover command on the storage controller that contains my_data_vol.
- D. Use the wafiron command against my_data_vol to solve the inconsistency on the volume.

Correct Answer: A

QUESTION 4

You are trying to deploy a Connector in the AWScloud from NetApp Cloud Manager. The deployment fails and shows the message "\\Insufficient permissions to deploy Cloud Connector". You have verified the AWS access key and the AWS secret key.

In this scenario, what is the reason that the deployment failed?

- A. No AWS Marketplace subscription is associated with Cloud Manager.
- B. The required Identity and Access Management (IAM) policies were not installed.
- C. The user lacks the permission to deploy within Cloud Manager.
- D. The Connector can be deployed only in AWS GovCloud (US).

Correct Answer: C

QUESTION 5

Your customer has deployed a two petabyte NetApp ONTAP FlexGroup volume across their 4-node ONIAP 9.8 cluster. They plan to store over three billion files. They want to prevent file 10 conflicts since files are placed into the FlexGroup volume.

In this scenario, which two NFS SVM parameters should be enabled? (Choose two.)

- A. -v3-64bit-identifiers
- B. -v4-fsid-change
- C. -v3-fsid-change
- D. -v4-64bit-identifiers

Correct Answer: AC

QUESTION 6

You are attempting to connect a NetApp ONTAP cluster to a very complex network that requires LIFs to fail over across subnets. How would you accomplish this task?

- A. Configure an equal number of LIFs on each subnet.
- B. Configure VIP LIFs using OSPF.
- C. Configure VIP LIFs using BGP.
- D. Configure a LIF failover policy for each subnet inside a single broadcast domain.

Correct Answer: C

QUESTION 7

A customer with an FC MetroCluster configuration that is running NetApp ONTAP 9.8 software experienced a site outage and wants to know why the MetroCluster configuration did not switch over to the other site. What are two reasons for this problem? (Choose two.)

- A. There was a failed PSU in the switchover site.
- B. The ISLs were down between the sites.
- C. The site had unmirrored aggregates.
- D. An ISL link was not operating at 16Gbps.

Correct Answer: AC

QUESTION 8

When you review performance data for a NetApp ONTAP cluster node, there are back-to-back (B2B) type consistency points (CPs) found occurring on the root aggregate.

In this scenario, how will performance of the client operations on the data aggregates be affected?

- A. During B2B processing, clients will be unable to write data.
- B. Data aggregates will not be affected by B2B processing on another aggregate.
- C. During B2B processing, all I/O to the node is stopped.
- D. During B2B processing, clients will be unable to read data.

Correct Answer: B

QUESTION 9

A customer reports that some of their client computers are unable to access a FlexGroup over CIFS. This problem involves only their older Windows XP clients and some printers and scanners.

In this scenario, which statement is correct?

- A. FlexGroup requires CIFS shares to be located in qtrees, which these clients do not support.
- B. FlexGroup requires CIFS shares to use the Continuously Available Feature, which these clients do not support.
- C. These systems use the SMQI protocol which is an unsupported feature in FlexGroup.
- D. These systems use Offloaded Data Transfer, which is an unsupported feature in FlexGroup.

Correct Answer: B

QUESTION 10

Your customer added a new DS4246 shelf to their FAS2750 single-node system and created a new aggregate on the new shelf. Two weeks later, they log into Active IQ and discover the Medium Impact error shown below. Shelves with both connections via the same SAS path detected

```
===== SAS-EXPANDER-MAP =====
Expanders on channel 0a:
Level 1: WWN 500a098005f0ed3f, ID 0, Serial Number ' SHJHU1527000148', Product
'DS424IOM6E ', Rev '0172', Slot A
Level 2: WWN 500a098005b053bf, ID 1, Serial Number ' SHFPHU1516001218', Product
'DS224IOM6 ', Rev '0191', Slot A
Level 3: WWN 500a09800772e3bf, ID 2, Serial Number ' SHJHU1653000119', Product
'DS424IOM6 ', Rev '0191', Slot A
Level 4: WWN 500a098005af77bf, ID 1, Serial Number ' SHFPHU1516001218', Product
'DS224IOM6 ', Rev '0191', Slot B
Level 5: WWN 500a09800773b8bf, ID 2, Serial Number ' SHJHU1653000119', Product
'DS424IOM6 ', Rev '0191', Slot B

Expanders on channel 0b:
Level 1: WWN 500a09800773b8bf, ID 2, Serial Number ' SHJHU1653000119', Product
'DS424IOM6 ', Rev '0191', Slot B
Level 2: WWN 500a098005af77bf, ID 1, Serial Number ' SHFPHU1516001218', Product
'DS224IOM6 ', Rev '0191', Slot B
Level 3: WWN 500a09800772e3bf, ID 2, Serial Number ' SHJHU1653000119', Product
'DS424IOM6 ', Rev '0191', Slot A
Level 4: WWN 500a098005b053bf, ID 1, Serial Number ' SHFPHU1516001218', Product
'DS224IOM6 ', Rev '0191', Slot A
Level 5: WWN 500a098005f0ed3f, ID 0, Serial Number ' SHJHU1527000148', Product
'DS424IOM6E ', Rev '0172', Slot A
```

Referring to the exhibit, which statement is correct?

- A. In a FAS2750 system, the internal shelf is only seen on one path, and the external shelves are seen on two paths.
- B. The cables are cabled Incorrectly on the SAS stack.
- C. This situation is normal for a FA57750 single-node system.
- D. Active IQ Is not aware of the shelf configuration for a single-node system.

Correct Answer: C

[NS0-593 PDF Dumps](#)

[NS0-593 VCE Dumps](#)

[NS0-593 Exam Questions](#)