

500-920^{Q&As}

Cisco Data Center Unified Computing Infrastructure Troubleshooting
(DCITUC)

Pass Cisco 500-920 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.certbus.com/500-920.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



QUESTION 1

Which two formats can be configured for Cisco's Call Home email message? (Choose two)

- A. JSON
- B. CSV
- C. Full text
- D. XML

Correct Answer: CD

<http://www.audentia-gestion.fr/cisco/smart-call-home-feature-guide-1611.pdf>

Call Home Message Formats The Call Home feature offers the following message formats:

Short Text -- Suitable for pagers or printed reports.

Plain Text -- Full formatted message information suitable for human reading.

XML -- Matching readable format using Extensible Markup Language (XML) and Adaptive Markup Language (AML) document type definitions (DTDs).

The XML format enables communication with the Cisco TAC. For user- defined destination profiles, the format options are long-text, short-text, or XML. The default is XML. For the predefined Cisco TAC profile, only XML is allowed.

QUESTION 2

Which statement is true regarding the UCS Manager GUI is showing "Overall Status Unassociated" in the General tab for a C-series server?

- A. The server has a service profile assigned, but has connectivity issues with UCS Manager
- B. The server is not properly connected
- C. The server does not have a service profile assigned, but has been discovered by UCS Manager
- D. The server has been properly connected, but has not been discovered by UCS Manager

Correct Answer: B

QUESTION 3

The command show interface veth 705 is telling you that the bound interface is Ethernet 3/1/2

What is the location of the blade that has veth 705 associated to it?

- A. Chassis 3, Slot 1
- B. Chassis 3. Slot 2
- C. There is not enough information
- D. Chassis 1. Slot 2

Correct Answer: A

QUESTION 4

The UCS Chassis Discovery Policy has been set to four and a new chassis is connected with two links What is the resulting chassis recognition action?

- A. The chassis will not be recognized
- B. The Chassis Discovery Policy will automatically reset to two links, since it always tracks the physical connections
- C. The chassis will be recognized and both links will be active
- D. The chassis will be recognized but only one of the links will be active.

Correct Answer: A

QUESTION 5

After performing a UCS firmware upgrade, which two UCS components will require updated drivers? (Choose two)

- A. VIC Cards and Fiber Channel HBAs
- B. Cisco Fabric Interconnects
- C. Cisco UCS Manager
- D. RAID Controllers

Correct Answer: AB

QUESTION 6

Which statement is true when using SPAN for Fibre Channel (FC) Traffic?

- A. FC port on Cisco UCS 6238UP can be used as a SPAN source
- B. When defining FC uplink port as the SPAN destination, system will automatically stop using that port as an uplink port

C. Any port can be used as a SPAN destination port Even if it is defined as Eth uplink port it will be automatically converted to FC uplink port

D. For FC SPAN sessions we do not have to specifically enable the monitoring session

Correct Answer: A

QUESTION 7

In a Cisco UCS Manager, if all KVM sessions to each server fail to start, what is likely causing the problem?

A. Cisco UCS Manager has a problem

B. The Fabric Interconnect to which you are connected has a problem

C. The I/O Modules in the chassis are the problem

D. The workstation you are using to connect to the KVM session is the problem

Correct Answer: D

QUESTION 8

You are experiencing intermittent connectivity issues on one specific Cisco UCS server Some applications work, while other do not transfer data You suspect jumbo frames limitations

Which two places do you check the jumbo frame settings? (Choose two)

A. Check server's service profile and/or service profile template

B. Check server's QoS System Class

C. Check the fibre channel port configuration for jumbo frame configuration

D. Check upstream switch ports frame size configuration

E. Check server's individual vNICs and/or vHBAs properties

Correct Answer: BD

QUESTION 9

When configuring UCS SAN Connectivity to a 3rd Party FibreChannel Storage Array that is connecting directly to the UCS Fabric Interconnects, which option is Cisco recommended?

A. Connect the Storage Array to a RC Storage Port and Enable NPV Mode on the UCS Fabric Interconnects

B. Connect the Storage Array to an Appliance Port and Enable NPV Mode on the UCS Fabric Interconnects

- C. Direct connectivity between UCS Fabric Interconnects and FibreChannel Storage Arrays is not supported
- D. Connect the Storage Array to a FC Storage Port and Enable Switching Mode on the UCS Fabric Interconnects
- E. Connect the Storage Array to an Appliance Port and Enable Switching Mode on the UCS Fabric Interconnects

Correct Answer: D

QUESTION 10

Which two statements describes connecting the IO Modules in the UCS chassis to the Fabric interconnects? (Choose two)

- A. Connect FI-A to the IOM B of each chassis
- B. Connect FI-B to IOM A and IOM B in each chassis
- C. Connect FI-A to the IOM A of each chassis
- D. Connect FI-A to IOM A and IOM B in each chassis
- E. Connect FI-B to the IOM A of each chassis
- F. Connect FI-B to the IOM B of each chassis

Correct Answer: ACF

[Latest 500-920 Dumps](#)

[500-920 VCE Dumps](#)

[500-920 Practice Test](#)